L Number	Hits	Search Text	DB	Time stamp
1	1	(brak$4 same (degrad$5 or wear or fading))and (fluid near4 leakage)and (wheel near3 lock)and (brak$4 near3 effectiveness)and (brake near4 position near4 sensor)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 09:36
2	91	(brak$4 same (degrad$5 or wear or fading))and (brake near4 position near4 sensor)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 09:44
3	1	(brak$4 same (degrad$5 or wear or fading))and (brake near4 position near4 sensor)and ABS and (friction near3 coefficient)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 09:38
4	14	(brak$4 same (degrad$5 or wear or fading))and (brake near4 position near4 sensor)and ABS	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 09:39
5	45	(brak$4 same (degrad$5 or wear or fading))and (brake near4 position near4 sensor)and (brak$4 near4 pressure)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 10:04
10	4	(wheel near3 lock)and (brak$4 near4 effectiveness)and (brake near2 position near3 sensor)and (brake near3 pressure)and deceleration	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 10:06
9	5	(wheel near3 lock)and (brak$4 near4 effectiveness)and (brake near2 position near3 sensor)and (brake near3 pressure)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 10:11
8	6	(wheel near3 lock)and (brak$4 near4 effectiveness)and (brake near2 position near3 sensor)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 10:13
13	18	((brake near3 wear)or (brak$4 near4 effectiveness)or (brake near3 fading))and (brake near2 position near3 sensor)and deceleration	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/05/29 10:15